DPM2292-2

A00

U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

<u> </u>						
Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)						
		SECT	TON t	-		
SECTION I MANUFACTURER'S NAME EMERGENCY TELEPHONE NO.						
Products Research & Chemical Corp. (213) 849-3992						
ADDRESS (Number, Street, City, State, and ZIP Code)						
2919 Empire Ave., Burbank, Calif. 91504 CHEMICAL NAME AND SYNONYMS TRADE NAME AND SYNONYMS						
Polysulfide sealing compound. PR-1422 Class A CHEMICAL FAMILY FORMULA						
N/A N/A						
SECTION	111 -	HAZAF	RDOUS INGREDIENTS			
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)	
PIGMENTS			BASE METAL			
CATALYST Calcium Dichromate	4	0.1mg/	ALLOYS			
VEHICLE		L	METALLIC COATINGS			
solvents Toluene	7	200ppm	FILLER METAL PLUS COATING OR CORE FLUX			
жажжжы Methyl ethyl ketone	2	200ppm	OTHERS			
отнеяя Dimethyl formamide	2	10ppm	<u> </u>	_		
HAZARDOUS MIXTURE					TLV (Units)	
						
				_		
SEC	TIO	N III - P	HYSICAL DATA			
BOILING POINT (°F.)			SPECIFIC GRAVITY (H ₂ O=1)	1	.42	
VAPOR PRESSURE (mm Hg.)	+	N/A N/A	PERCENT, VOLATILE 16 CO/			
VAPOR DENSITY (AIR=1)	1	N/A	EVAPORATION RATE		1/A	
SOLUBILITY IN WATER	1	nsol.		<u> </u>	···	
APPEARANCE AND COOR Light brown			ene odor.			
			·			
SECTION IV -	FIR	E AND E	EXPLOSION HAZARD DATA			
FLASH POINT (Method used) 23°F (PMI	CC)		FLAMMABLE LIMITS Lel		- Uel	
EXTINGUISHING MEDIA		form	ro			
Dry chemi	<u> </u>	ı uciii,	•			
		,				
UNUSUAL FIRE AND EXPLOSION HAZARDS						

SECTION V - HEALTH HAZARD DATA	_
THRESHOLD LIMIT VALUE 200 ppm .	
EFFECTS OF OVEREXPOSURE Headache: possible skin irritation.	
EMERGENCY AND FIRST AID PROCEDURES SKIN: Wash thoroughly with soap and water.	
EYES: Wash out immediately with plenty of water; see a physician.	
INHALATION: Remove to fresh air.	

			SECTIO	ON VI - RE	ACTIVITY DATA	
STABILITY	UNSTABLE		CONDITION	CONDITIONS TO AVOID		
STABLE X						
INCOMPATABILI	TY (Mate	rials to avoid)	Can	react with	reducing materials.	
HAZARDOUS DE	COMPOS	ITION PRODUC	TS		ur; hydrogen sulfide ,formic acid.	
HAZARDOUS		MAY OCCUR	-		CONDITIONS TO AVOID	
POLYMERIZATIO	NC	WILL NOT O	CCUR	Х		
	•	•				

SECTION VII - SPILL OR LEAK PROCEDURES
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Wipe up with rags or paper towels: clean with MEK.
WASTE DISPOSAL METHOD Closed containers in normal trash route.
Do not incinerate.

	SECTION VIII - SPEC	CIAL PROTECTION	ON INFORMATION	
	ROTECTION Specify type.	4		
VENTILATION	ed respirator in enclose LOCAL EXHAUST Adequate to minimize		SPECIAL	
	MECHANICAL (General)		OTHER	
Gloves or	oves hand cream.	EYE PROTI Chemica	ection I goggles optional.	
OTHER PROTECT	IVE EQUIPMENT			

SECTION IX - SPECIAL PRECAUTIONS
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Keep in closed containers in sheltered area.
Keep away from heat and open flame.
OTHER PRECAUTIONS Avoid prolonged skin contact. Avoid prolonged or repeated breathing of vapor.